Confined Space Entry & Tunnel Safety – Appendix C: Confined Space Index – Cascade Campus

The following table provides index and initial space classification for spaces at **Cascade Campus**. The numbers noted are related to notation on maps.

| Map Location # | Building/Location | Space Type or Name / Conditions | Space Classification | Hazards |
|-------------------|--|---|--------------------------|---|
| 100 - Vault w | ith Single / Double and Triple Square Covers | | | 1 |
| Outside location | ons throughout the campus includes: Backflow | Preventer Vaults, FDC valves | and electrical vaults | |
| 101 | PSEB parking lot on south side next to | Storm water Management | not a confined space | |
| | Killingsworth | system vault | | |
| 102x | Through campus parking lots, open yards, | Sewer Manholes – There are | Permit-Required Confined | Atmospheric hazards |
| 102 a 102 b | sideways and internal streets | most likely additional. | Space | Sewer/water flow – |
| 102 b | a. PSEB Parking lot east side at least 3 manholes | | | engulfment. |
| 102 d | b. TH entrance area from parking lot | | | Pathogenic micro-organism |
| 102 d 102 e | Handicap | | | contact – infectious |
| 102 e | c. to f. are all in sideway and lawn into | | | diseases. |
| 102 g. | Jackson Hall | | | Possible physical hazards form falling an aligning. |
| 102 g. 102 h. | g. NE each side to JH at P-2 parking | | | from falling or slipping. |
| 102 i | h. P-2 parking lot | | | |
| 102 j. | i. Jackson Hall front grass | | | |
| 102 k. | j. 4 sewer manholes in yard north of Arts and | | | |
| 102 I. | Humanities | | | |
| | k. SW side of Terrel Hall | | | |
| | New SC parking garage. Number of standard sewer manholes | | | |
| 104 | Terrell Hall Kerby and Jessup St merge corner | Water Meter: Single metal square hatch covering. | not a confined space | |
| 105 | SE side of Jackson, next to P2 parking | Irrigation Backflow Device: Vault cover at building partially in the bushes | not a confined space | |
| 106 | SE side, next to P-2 parking Jackson Hall | FDC Backflow and Valves: | Permit-Required Confined | Atmospheric hazards |
| | | Single square 2'x3' metal | Space | Falling or slipping |
| | | cover for the FDC in | | High pressure water lines – |
| | | background | | engulfment |
| 107 | South side of Jackson Hall | Electrical transform, double | not a confined space | |
| | | square entry vault for conduit | | |
| 100 | <u> </u> | 4 feet deep. | | |
| 108 | NE side of Technology Building | Electrical transform, double | Permit-Required Confined | Electrical hazards |
| | | square entry vault for conduit | Space | Oxygen deficiency |
| 400 | NE dita di Tanta da Pali Para | 4 feet deep. | and a serificant areas | Falls |
| 109 | NE side of Technology Building | Transformer vault double metal hatch with conduit vault | not a confined space | |
| | | 4 feet deep. | | |

Rev. FEB 2025

| Map Location # | Building/Location | Space Type or Name / Conditions | Initial Classification | Hazards |
|-------------------|--|--|--------------------------------|--|
| 110 CACV004 | Sidewalk at SW corner Technology Bldg. on Killingsworth. | Communication Vault: Single square metal hatch – TELEPHONE 4 feet deep. | not a confined space | |
| 111 | Sidewalk at SW corner Technology Bldg. on Killingsworth | Water Vault/Valves Single square metal hatch 8' deep. | Permit-Required Confined Space | Atmospheric hazards Falling or slipping High pressure water lines – engulfment |
| 112 | Sidewalk at SW corner Technology Bldg. on Killingsworth | Water Meter 2' deep: Double square metal hatch. | not a confined space | |
| 113 | Sidewalk at SW corner Technology Bldg. on Killingsworth | Water Meter 2' deep: Double square metal hatch. | not a confined space | |
| 114 | W Entrance sidewalk to Technology on Kerby Ave. | Fire Water Line: Single metal hatch in the bark dust 3'x'3 and 8' deep. | Permit-Required Confined Space | Atmospheric hazards Falling or slipping High pressure water lines – engulfment |
| 116 | Loading dock on Library along Kerby Ave. | Electrical Room with Switch Gear opened annual for inspection: Large metal grate with locked hatch entry 12 feet deep. Electrical secured room with continuous ventilation. Enclosed electrical space. | Permit-Required Confined Space | Electrical hazardsFalls |
| 117 | East side of Library against the air intake louvers | Electrical 2 feet deep Small double metal hatch vault | not a confined space | |
| 118 CACV011 | Between CS113 & CS119 in sidewalk S of Library on Killingsworth St. | Communication: Metal vault cover <4 feet deep | not a confined space | |
| 119 CACV003 | E Sidewalk at Arts Bldg. next to Killingsworth | Communications, 4 feet deep, Double metal vault | not a confined space | |
| 120 | E Sidewalk at entrance door Arts Bldg. next to Killingsworth | Communications, 4 feet deep, Double metal vault | not a confined space | |
| 121 | MAHB – courtyard side next to fence is FDC vault | Water Meter Double metal hatch vault | Permit-Required Confined Space | Atmospheric hazards Falling or slipping High pressure water lines – engulfment |
| 122 | Arts Bldg, center yard | Water Meter Single metal hatch cover | Permit-Required Confined Space | Atmospheric hazards Falling or slipping High pressure water lines – engulfment |
| 126 | Courtyard between SS and Arts Buildings (MAHB), in fenced area at Arts | Electrical transformer with double metal hatch vault 4' with conduit | Permit-Required Confined Space | Electrical hazards Falls |

| Map Location # | Building/Location | Space Type or Name / Conditions | Initial Classification | Hazards |
|-------------------|---|--|--------------------------------|--|
| 127 | Fenced area on NE side of MAHB courtyard | Fire Water Backflow Preventer: Double metal hatched vault 3'x3' and 8 feet deep | Permit-Required Confined Space | Atmospheric hazards Falling or slipping High pressure water lines – engulfment |
| 128 | West side of the Arts Building outside in center of block sidewalk. | Communication: Single metal hatch 2'x'2 and 4'deep. | not a confined space | |
| 129 CACV006 | East corner of SS telephone vault in courtyard. | Communication: Single metal hatch telephone vault 4' deep. | not a confined space | |
| 130 | West Side of Terrel Hall in yard at wall. | Backflow Preventer on the FDC single metal hatch 8 feet deep. | Permit-Required Confined Space | Atmospheric hazards Falling or slipping High pressure water lines – engulfment |
| 131 | West Side of Terrel Hall in yard at wall. | Domestic Water Valves and Backflow Preventer Shut-offs only 2 feet deep with 2 single metal hatches next to the FDC. | not a confined space | |
| 133 | West Side of Terrel Hall in sidewalk between SS and TH. | Storm water filters: 6'deep with double bolted down metal hatch plates. | Permit-Required Confined Space | Atmospheric hazards Water flow – engulfment. Micro-organism contact Possible physical hazards |
| 134 | North side of SS building by Albina Ave. and Jessup. | Fire Water Valves and Backflow; Double metal hatch vault for the FDC 8' deep. | Permit-Required Confined Space | Atmospheric hazardsFalling or slippingWater lines – engulfment |
| 135 | North side of SS building by Albina Ave. | Water Meter 2' deep: Double metal hatch vault. | not a confined space | |
| 136 | PE Building at Parking P-3 in grass area | Fire and Domestic Water Valves and Backflows with double open vault 8' deep. | Permit-Required Confined Space | Atmospheric hazards Falling or slipping High pressure water lines – engulfment |
| 137 | North corner of PSEB building water vault with backflow device on corner of N Michigan and Jessup St. | Fire and Domestic Water Valves and Backflows vault about 8' deep. | Permit-Required Confined Space | Atmospheric hazards Falling or slipping High pressure water lines – physical pressure and drowning |
| 138 | North Entrance to Terrel Hall. | 2' x3' red cover – Electrical vault. | Permit-Required Confined Space | Electrical hazards Falls |
| 139 | Student Center Underground Parking Garage At 4D parking area. | Valve double cover vaults | not a confined space | |

| Map Location # | Building/Location | Space Type or Name / Conditions | Initial Classification | Hazards |
|-------------------|--|--|--------------------------------|--|
| 140 | Student Center Underground Parking Garage At 4C parking area. | Two sewer manhole covers | Permit-Required Confined Space | Atmospheric hazards Sewer/water flow – engulfment. Pathogenic micro-organism contact – infectious diseases. Possible physical hazards |
| 141 | Student Center Underground Parking main entrance 3C area. | Triple electrical vault | Permit-Required Confined Space | Electrical hazards Falls |
| 142 | Student Center Underground Parking main entrance 3C area. | Double hatch electrical vault | Permit-Required Confined Space | Electrical hazards Falls |
| 143 | Student Center Underground Parking main ramp in and out of the garage. | Large round manhole cover – sealed, not sure purpose. | Permit-Required Confined Space | Atmospheric hazards Sewer/water flow – engulfment. Possible physical hazards |
| 144 | Student Center Loading area between the building and parking ramp. | Double square hatch vault - Electrical | Permit-Required Confined Space | Electrical hazards Falls |
| 145 | Student Center Loading area between the building and parking ramp | Two grease trap manhole covers for the vault and filter equipment. | Permit-Required Confined Space | Atmospheric hazardsWater flow – engulfment.Possible physical hazards |
| CACV001 | South of Student Services in Borthwick Ave walkway across from Library ramp. | Large vault with large round lid. Telecommunications | Permit-Required Confined Space | Low voltage electrical systemsOxygen deficiencyFalls |
| CACV002 | South of Jackson Hall in grass along Kerby Ave. (next to CACV009) | Large vault with large round lid. Telecommunications Water hazard | Permit-Required Confined Space | Low voltage electrical systemsOxygen deficiencyFalls |
| CACV008 | In walkway apron SW of MCTB at Kerby Ave. & Killingsworth St. | Large vault with large round lid. Telecommunications | Permit-Required Confined Space | Low voltage electrical systemsOxygen deficiencyFalls |
| CACV009 | South of Jackson Hall in walkway along Kerby Ave. (next to CACV002) | Large vault with large round lid. Telecommunications Water hazard | Permit-Required Confined Space | Low voltage electrical systemsOxygen deficiencyFalls |
| CACV012 | Between CS118 & CS119 in sidewalk SW of Library on Killingsworth St. | Small square vault cover, UNKNOWN | Permit-Required Confined Space | Possible atmospheric hazards Water flow – engulfment. Possible physical hazards |

| Map Location # | Building/Location | Space Type or Name / Conditions | Initial Classification | Hazards |
|-------------------|---|---|--------------------------------|---|
| CACV013 | North of PE Bldg on Killingsworth St. sidewalk | Square vault cover, UNKNOWN | Permit-Required Confined Space | Possible atmospheric hazards Water flow – engulfment. Possible physical hazards |
| | System and Facilities Access Hatches | • | | |
| 201 | Student Center, basement. Room labeled Sprinkler Control Valve. | Square entry to pipe chase from the Sprinkler Control Room – Labeled as 'Asbestos Hazard' – However, asbestos been removed, too small for access. | not a confined space | |
| 300- HVAC Co | poling Tower and HVAC Units | | | |
| 301 | PSEB roof access to HVAC system filter area. | HVAC filter panel and coils. | Confined Space | |
| 302 | PSEB roof unit. | Air handling unit. | Confined Space | |
| 303 | PSEB air handling chilling unit. | Several ½ door entry points for repair and maintenance. | Confined Space | |
| Map Location # | Building/Location | Space Type or Name / Conditions | Initial Classification | Hazards |
| 304 | Student Services top floor mechanical room. | HVAC units with hatches to the filters and coils and fans. | Confined Space | |
| 305 | Margaret Carter Technology Building. | Cooling tower along back alley facing N Commercial Ave. No access. | Confined Space | (LO/TO required) |
| Map Location # | Building/Location | Space Type or Name | Initial Classification | |
| 306 | Library loading dock. | Large air conditioning system. LO/TO required | Confined Space | |
| 307 | Student Union parking garage exhaust fan | Exhaust fan air handler. | not a confined space | |
| 400 - Boiler S | | 1 | | |
| 400 | All facilities | Boiler Systems Note: NEW boilers are not confined spaces – Cannot be entered Ductwork is also too small to enter. | Confined Space | |
| 500 - Tanks | | | | |
| 500 | None | | | |
| | ATED and SUMP PUMP SPACES | T | T | |
| See 102x | None | | | |

