

PCC Confined Space Index revised 8/13/15
Southeast Campus

The following table provides index and initial space classification for spaces at Sylvania Campus. The numbers noted are related to notation on maps.

Map Location #	Building/Location	Space Type or Name	Initial Classification
100	Outside locations throughout the campus	Outside square single, double and triple door vaults, manholes	
101.xx	These manholes are throughout the Parking Lots and entrance areas	Sewer Manhole Covers	Permit
102	Southwest corner of Mt. Tabor next to entrance from Division Street	Telephone manhole vault cover	Permit
103	Southwest area of Mt. Tabor at the solid waste dumpsters	Electrical manhole vault covers (2)	Permit
104	Southwest area of Mt. Tabor by the emergency generator	Double metal vault – shallow electrical wire connection	Shallow electrical Not confined space
105	Southwest area of Mt. Tabor by the emergency generator	Electrical transformer with a single metal hatch cover over the vault	Permit
106 a., b., and c.	West side of Mt. Tabor – new driveway entrance from Division. 3 Manholes for the Cafeteria Grease Traps	Grease Traps, generally no entry vacuum system used to remove the grease. About 6 feet deep and are on sewer line.	Permit
107	South side of Mt. Tabor facing the Library	Square hatch labeled Electric	Permit – PGE only
108.x	Library on Division St Side and between Mt. Tabor and the Library Bldg. One in front of the Grounds FMS storeroom	Double Hatch Communication vaults (number of them) they are all very shallow – wire vaults	Not a confined space
109	Between the Library on Division St. Side and Administration Building	Triple Electrical Vault	Permit/Alternate
110	South side of Student Commons facing Bank of West Parking Area	Electrical transformer vault	Permit/Alternate
Next to 110 see 201 and 202 interior opening to same space	In wall of the Student Commons building is access to under the inside stairwell	Access to building stairwell has airflow from the building, no hazards, no fall hazards.	Confined Space but NON-Permit
111	Library on Division St. side by SE Center Sign showing direction of Permit Parking	Double Vault 5 by 8 feet in with and length and 8 feet deep	Permit may be Alternate based on specific vault conditions.
112	Between Library and Bank of the West walkway (In the sidewalk)	Double hatch backflow water vault (City of Portland with blue marking)	Permit/Alternate
113	Next to 112 in the bark dust	Single hatch vault – most likely associated with the water	Permit/Alternate

**PCC Confined Space Index revised 8/13/15
Southeast Campus**

Map Location #	Building/Location	Space Type or Name	Initial Classification
114	In front of the library from the sidewalk between Library and Bank of the West in the barkdust	Double hatch vault – Electric Vault	Permit / PGE
115	In front of Administration Building on Division St.	Double hatch water backflow vault	Permit/Alternate
116	In front of Administration Building on Division St.	Triple hatched PGE Electrical Vault	Permit
117	In front of the Landscape – Grounds FMS store room	Triple hatched PGE Electrical Vault	Permit
118	NW corner of the Administration Building by a cage with AC units (behind the building)	Single hatch with space 105 inches deep; housing wiring connections.	Permit/Alternate
200 Facilities Access Hatches		Square Hatch Openings	
201	South end of the stairs at Mt. Scott main entrance	Hatch to enter the building chase – space behind the stairs no hazards air from building	Confined space but non-permit
202	North end of the stairs at Mt Scott by the entrance	Hatch to enter the building chase (same above)	Confined space but non-permit
203	Elevator Pit in Mt Scott	Access to the elevator pit none	No confined space
300	HVAC Cooling Tower and HVAC Units		
301	Mt Tabor Roof	Cooling Tower	Permit /Alternate for entry into the Cooling tower
Boiler Systems Note: new boilers are not confined spaces – cannot be entered (no access and small) Ductwork is also too small to enter			
ARTS			
400	Mt. Tabor Ceramics Kilns	Too small to enter	Not Confined Spaces
401	Mt. Tabor Ceramics	Clay Trap about 4 feet deep and has been dug out	Too shallow for entry.